



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information

Current owner Charles & Karen Bertlshoser
 Buyer _____ Realtor Froise Reed Estate
 Mailing address 1982 230th St Donnan Iowa
 Site Address/County 1982 230th St Donnan Iowa
 Legal Description _____

No. of bedrooms 3 Last occupied? Still Records available yes

Permit/installation date Jun 21-1978 Separation distances ok/no? _____

Septic system information

Septic tank(s): size 1000 material concrete condition decat
 Tank pumped? yes date 11-17-2021 licensed pumper ST-99
 Septic/trash/processing tank: size na material na condition na
 Tank pumped? no date na licensed pumper no

Aerobic treatment unit (ATU) mfrg none size na
 Tank pumped? no date na licensed pumper na
 Maintenance contract? no expiration date na service provider no
 Condition na

Pump tanks/vaults: type no size na condition na

Distribution system: distribution box no outlets used na condition no
 Header pipe(s) no # of lines na Pressure dosed? no

Secondary treatment:

length of absorption fields none determined by Report
 condition of fields none determined by Report
 type of trench material na

Size of sand filter none determined by Report
 Vent pipes above grade? no discharge pipe located? yes
 Effluent sample taken? yes Results C66 9.0 DJG 6.0

Media filters: type na
 Maintenance contract? no expiration date na service provider na
 Condition na

NPDES General Permit No. 4: required? no permitted? yes NOI provided no



Time of Transfer Inspection Report

Other components:

Alarms no Working? no disinfection no working? no

Control box no Timers no inspection ports no

Other components none

Overall condition of the private sewage disposal system

Report system status as of this date is in working order!

Explain (attach additional pages as needed): on Report

Comments: System is working Fine to Date!

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector: [Signature] Date: 11-22-2021
 Name (print): Glen A Meyers Certificate #: 8728
 Address: P.O. Box 498 Keokuk IA 52132
 Phone #: 319-524-7329

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office, and to;

Iowa DNR
Private Sewage Disposal Program
502 E. 9th St.
Des Moines, IA 50319

11/22/2021

Subject: Report
From: "Glen Meyers" <gldrivesetank@qwestoffice.net>
Sent: 11/22/2021 9:20:50 AM
To: "Glen Meyers" <gldrivesetank@qwestoffice.net>;

11-22-2021

Meyers Septic Service
P.O. Box 488
Keokuk Iowa 52632

Septic Inspection: 1982 230th st Donellson Iowa

After doing Septic inspection at above property this system is in working order to date. This is a permitted Lagoon system which is still in working order. For the age of this system it was put in per chapter 69 code per year of 1974. If anything happens to this system in the future it will have to be brought up to current codes.

Thank You



Owner

1-319-524-7329











